



**GARY R. HERBERT**  
Governor

**GREG BELL**  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

**MICHAEL R. STYLER**  
Executive Director

### Division of Oil, Gas and Mining

**JOHN R. BAZA**  
Division Director

#### Representatives Present During the Inspection:

Company	Dennis Oakley
OGM	Steve Demczak

## Inspection Report

Permit Number:	C0150017
Inspection Type:	COMPLETE
Inspection Date:	Monday, May 16, 2011
Start Date/Time:	5/16/2011 10:00:00 AM
End Date/Time:	5/16/2011 2:00:00 PM
Last Inspection:	Monday, April 18, 2011

Inspector: Steve Demczak

Weather: Partly Cloudy, 60's

InspectionID Report Number: 2745

Accepted by: jhelfric

5/19/2011

Permittee: **ENERGY WEST MINING CO**

Operator: **ENERGY WEST MINING CO**

Site: **DES BEE DOVE MINE**

Address: **PO BOX 310, HUNTINGTON UT 84528**

County: **EMERY**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **RECLAIMED**

#### Current Acreages

133.90	<b>Total Permitted</b>
40.90	<b>Total Disturbed</b>
136.58	<b>Phase I</b>
95.70	<b>Phase II</b>
95.70	<b>Phase III</b>

#### Mineral Ownership

- ☒ Federal  
☐ State  
☐ County  
☒ Fee  
☐ Other

#### Types of Operations

- ☒ Underground  
☐ Surface  
☐ Loadout  
☐ Processing  
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violation were issued.

Inspector's Signature:

*Steve Demczak*  
Steve Demczak,

Inspector ID Number: 39

Date

Monday, May 16, 2011



Note: This report is not a permit. It is a record of an inspection. It does not constitute a guarantee of the accuracy of the information provided. The Division of Oil, Gas and Mining is not responsible for the accuracy of the information provided. The Division of Oil, Gas and Mining is not responsible for the accuracy of the information provided.

telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • [www.ogm.utah.gov](http://www.ogm.utah.gov)

Permit Number: C0150017  
 Inspection Type: COMPLETE  
 Inspection Date: Monday, May 16, 2011

## Inspection Continuation Sheet

Page 2 of 4

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**1. Permits, Change, Transfer, Renewal, Sale**

The permittee has received a permit renewal from the Division. The DOGM permit will expire on Aug.30, 2015.

**2. Signs and Markers**

The identification signs is located on the trail to the mine site.

**3. Topsoil**

All topsoil was used in reclamation.

**4.a Hydrologic Balance: Diversions**

Diversions were spot-checked and would function in a storm event. There were no signs of water erosion to the diversion.

**4.c Hydrologic Balance: Other Sediment Control Measures**

The mine site is pocked to control sediment control.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

Refuse/coal fines were removed in reclamation.

**8. Noncoal Waste**

The area was clear of non-coal waste material.

**10. Slides and Other Damage**

No slides or other damage was noticed during the inspection.

**12. Backfilling And Grading**

The site is backfilled and graded to AOC standards in my opinion.

**13. Revegetation**

Vegetation is coming up throughout the property this past summer.

**15. Cessation of Operations**

The site is completely reclaimed.

**18. Support Facilities, Utility Installations**

There are no facilities at this site.

**19. AVS Check**

AVS checks are done at DOGM main office in SLC.

Permit Number: C0150017  
Inspection Type: COMPLETE  
Inspection Date: Monday, May 16, 2011

**Inspection Continuation Sheet**

*Page 4 of 4*

**21. Bonding and Insurance**

The insurance will expire on Aug. 28, 2011. The company affording coverage is ASSOC. Electric & Gas Ins Serv LTD. The bond amount is \$511,000. The reclamation agreement was inspected and was signed by both parties.